Date:

Monday, 9/10/2007 1:32:03 PM

User

Kim Johnston

Process Sheet

Customer Job Number : CU-DAR001 Dart Helicopters Services

: 34520 : 11800

Estimate Number P.O. Number

: Uha

This Issue

: 9/10/2007

S.O. No. : 4/1A

: NC, : 27584

Type

: PURCHASED PARTS

Part Number

Drawing Number

Drawing Name

Project Number

Drawing Revision Material

Due Date

: 10/2/2007

: N/A

: D25253

: SPACER KIT

· D2525 REV B

Qty:

Each Um:

Written By

Prsht Rev.

First Issue

Previous Run

Checked & Approved By

Comment

: Est. В

Re-format added Acid etch step EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

6061-T6 Round Bar .750"

1.0

M6061T6R0750



Comment: Qty.: 0.0231 f(s)/Unit

6061-T6 Round Bar .750"

Total:

0.4620 f(s)

2.0

LATHE CONV



Comment: CONVENTIONAL LATHE

Turn as per Dwg D2525

3.0 QC2





4.0

QC8







Comment: SECOND CHECK

HAND FINISHING RESOURCE #1




5.0

HAND FINISHING1



Comment: HAND FINISHING RESOURCE #1 Acid etch and Alodine as per QSI 005 4.1

Comment: INSPECT PARTS AS THEY COME OFF MACHINE



50

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION



Dart Aerospace Ltd

W /O:		WORK ORDER CHAN	IGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				-8-0		-7.1	
Part No		PAR #: Fault Category:	NCR: Yes	No DQ	A: <u></u>	Date: _	11/01/30
			QA:	N/C Close	d:	_ Date: _	

NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)	ICR)					
		Description of NC		Corrective Action Section E	}	Verification Section C	Approval Chief Eng	Approval QC Inspector			
DATE	ATE STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date							
								7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			
						:					
				,							
								-			
					į						

NOTE: Date & initial all entries

Monday, 9/10/2007 1:32:03 PM Úser: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: SPACER KIT Job Number: 34520 Part Number: D25253 Job Number: Seq. #: Machine Or Operation: Description: PACKAGING 1 7.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:___ 8.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion U St.10.30

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	NGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #: Fault Category:	NCR: Yes	No DO	Δ.	Date:	

QA: N/C Closed: ____ Date: ____

NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
	ATE STED Description of NC		Corrective Action Section B			Verification	Marification A			
DATE	STEP	Section A	InitialAction DescriptionSign &Chief EngChief EngDate		Section C	Approval Chief Eng	Approval QC Inspector			
								÷.		
		,								
		(*)								

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 34520
Description: Spacer Kit	Part Number: D2525-3
Inspection Dwg: D2525 Rev: B	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.515	+0.008/-0.001	0.5165				
Ø0.750	+0.008/-0.001	0.750	/			7
0.250	+/-0.010	0.5165	/			•
		 				
			,			

Measured by: DJP	Audited by:	ゴル	Prototype Approval:	N/A
Date: 07/10/27	Date:	07/10/27	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	06.08.29	New Issue	KJ/JLM O	Cill
			······································	7~,



		The state of the s
DESIGN BW	DRAWN BY	DART AEROSPACE LTD . HAWKESBURY, ONTARIO, CANADA
CHECKED	APPROVED	DRAWING NO. REV. I D2525 SHEET 1 OF
DATE		TITLE SCALI
99.09.30		SPACER KIT 1:
А	95.12.22	NEW ISSUE
8	99.09.30	REVISED MATERIAL

RELEASED

PART NUMBER	THICKNESS T	QTY
D2525-1	0.750	1
D2525-3	0.250	1
D2525-5	0.125	4
D2525-7	0.063	0
D2525-9	0.032	0



MATERIAL: 5052-H32 (QQ-A-225/7) OR 1100 (QQ-A-225/6) OR 6061-T6 (QQ-A-225/8) OR 6061-T6 (QQ-A-200/8) NTROLLED COPY

SHOP COPY

OR 6061-T6 (QQ-A-225/8) OR 6061-T6 (QQ-A-20Q/80) NTROLLED COPTINISH: ACID ETCH AND ALODINE PER DART QSI 005 4. SUBJECT TO AMENDMENT

WORK ORDER